

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police** Case No: **2016-00063102**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

Vehicle #1 was traveling Route 70 westbound in the area of Route 88. Vehicle #2 was directly in front of vehicle #1. While vehicle #2 was stopped in traffic for the red light traffic signal, vehicle #1 collided with it's rear end. Driver #1 stated she did realize vehicle #2 had moved forward and stopped. Furthermore, when she did realize vehicle #2 was stopped she attempted to stop yet was unable due to the wet road surface.


New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police

Case No: 2016-00063102



707 Bennetts Mill Rd
Jackson, NJ