

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00061297**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

Vehicle 2 traveling westbound on Route 88, approaching Allaire Road. Vehicle 1 attempting to make a left turn onto Route 88 westbound from the parking lot of 1715 Route 88.

Driver 2 stated he was traveling along when Vehicle 1 pulled out directly in front of him. Driver 2 stated he was braking and sounding his horn when he struck the rear of Vehicle 1.


Driver 1 stated she was exiting the parking lot of 1715 Route 88, attempting to make a left turn. Driver 1 saw Vehicle 2 approaching and believed she had enough time to make her turn. As she made her turn, she was struck from behind by Vehicle 1 and began to spin, ending up on the sidewalk of Route 88 westbound.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**Station: **Brick Police**

Case No: 2016-00061297



Princeton Avenue

