

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police** Case No: **2016-00057825**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

Vehicle #2 was traveling westbound on Rt. 88 West. Vehicle #1 was traveling westbound on Rt. 88 West.

Driver #1 stated he attempted to avoid an animal in the roadway and pulled onto the right shoulder and immediately pulled back onto the roadway.

Driver #2 stated she was traveling in the westbound lane and Vehicle #1 pulled into the roadway from the right shoulder directly ahead of her vehicle. Vehicle #2 was unable to avoid Vehicle #1 and struck the left side of the vehicle as it entered the roadway.

Both vehicles were moved prior to my arrival.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police

Case No: 2016-00057825

