

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00058064**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

Vehicle #2 was traveling (Eastbound) on RT 88, approaching the intersection of Burrsville Road. An unknown vehicle, who was stopped at the stop sign on the corner of Burrsville Road/RT 88, abruptly pulled onto RT 88 West in front of Vehicle #2, causing Vehicle #2 to make a sudden stop. Vehicle #1 was traveling behind Vehicle #2, was not able to stop, and struck Vehicle #2 in the rear.

Vehicle #2 driver stated she observed the unknown vehicle driver only look at the traffic traveling (Westbound) on RT 88 before pulling away from the stop sign. Vehicle #2 driver stated she was forced to a complete stop in the roadway to avoid hitting the unknown vehicle.

Vehicle #1 driver stated he was traveling (Eastbound) on RT 88, behind Vehicle #2 and pressed his brake pedal as far down as it would go when he observed Vehicle #2 stopped in front of him. Vehicle #1 driver stated when he pressed the brake pedal it did not feel like the brakes engaged at all and his vehicle never slowed down, causing him to strike the rear of Vehicle #2. Vehicle #1 driver also stated he did not have enough time or room in front of him to steer out of the way.

Vehicle #1 was in a safe location and Vehicle #1 driver advised he was going to use his AAA service to tow the vehicle to his mechanic.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police

Case No: 2016-00058064

