

New Jersey Police												Case Number			Page <u>2</u> of <u>4</u>		
Crash Investigation Report												2022-00026303					
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On April 16, 2022, at approximately 1343 hours, Ptl. Talty #303 and I, were dispatched to the area of At Home, located at 1930 Route 88 for the report of a hit and run accident.

Upon my arrival, I spoke with the owner of Vehicle #2 who stated while she was inside At Home, her vehicle was struck. When she walked back out to her vehicle, an unknown witness provided her with a license plate number and stated it was a silver GMC SUV that hit Vehicle #2 and left the area. Vehicle #2 was parked within the marked parking space. A large scratch with silver paint transfer was observed on the driver's side front fender/bumper area.

Surveillance video was able to capture the crash and showed Driver #1 exit the store, walk to her vehicle, and begin pulling straight through the open parking space in front of her. While passing through the parking space directly to the left of Vehicle #2, Vehicle #1 began to make a right turn into the parking aisle. While making the right turn to travel back towards the store, it appears the passenger side rear tire area of Vehicle #1 comes in contact with the driver's side front area of Vehicle #2.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Joseph W McGrath	277	Joseph T Pacitti	238	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01
Station: — Case No: 2022-00026303

145 Crash Description

I was able to make contact with Driver #1 via telephone and she confirmed she was at At Home and had red paint transfer on the rear passenger door of her vehicle, as well as, a small dent. She stated she did not know she struck the vehicle and was wearing noise canceling head phones so she did not hear the crash either.

Based on my observations, the surveillance video, and statements made by both parties, I determined Vehicle #1 to be at fault for the crash.

Joseph W McGrath


277

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2022-00026303

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



AT HOME
1930 ROUTE 88

Joseph W McGrath

Officer's Signature

277

Badge Number