

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2022-00026596			Page 2 of 4	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

A motor vehicle crash occurred in the intersection of Route 70 and Route 88.

My investigation revealed that both vehicles were traveling east on Route 70 through the intersection of Route 88.

Vehicle 2 was traveling in the center lane and vehicle 1 was traveling in the left lane when vehicle 1 drifted to the left impacting vehicle 2. Driver 1 caused the crash due to unsafe lane change and driver inattention.

Driver 1 stated that vehicle 2 drifted into their lane causing the crash.

Driver 2 stated that they were traveling east on Route 70 when vehicle 1 entered their lane of travel and crashed into them.

A witness observed the crash and provided me with the following statement: Vehicle 2 was traveling in the center lane when vehicle 1 drifted into the center lane crashing into vehicle 2.

The witness completed a Brick Township Witness Statement.

146. Officer's Signature Jeffrey Kenneth Maehl	147. Badge # 310	148. Reviewer Brian D Ulman	Badge # 215	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01

Station: Case No: 2022-00026596

145 Crash Description

***Vehicle 1 was a Hyundai Kona. Vehicle 2 was a Infiniti JX35

Jeffrey Kenneth Maehl

Officer's Signature

310

Badge Number

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01


Station:

Case No: 2022-00026596

144 Crash Diagram (NOT TO SCALE)



NOT TO SCALE



Jeffrey Kenneth Maehl

310