

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2022-00024641			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was traveling westbound on Route 88 and left the roadway to the right, impacting a utility pole approximately 500 feet east of Van Zile Road. No injuries were reported.

Vehicle #1 operator claimed she served to the right to avoid another vehicle traveling eastbound in the westbound lane on Route 88. Vehicle #1 operator stated she struck the utility pole while swerving to the right, off the roadway.

Vehicle #1 operator was arrested for DWI, later submitting breath samples indicating a BAC of .14%. Refer to Ptl. Marmer #304's case report for details.

Vehicle #1 impacted Verizon Utility Pole #BT259, snapping the pole completely in half. Vehicle #1 suffered side and front airbag deployment and was disabled in the roadway. Vehicle #1 was removed from the scene and impounded by D&L towing.

146. Officer's Signature Evan Charles Mancini	147. Badge # 282	148. Reviewer —	Badge # —	149. Case Status ☐ Pending ☒ Complete
--	---------------------	--------------------	--------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police

Code: 01

Station:

Case No: 2022-00024641

144 Crash Diagram (NOT TO SCALE)



Not To Scale

Evan Charles Mancini

282