

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00053007**

(Refer to vehicle by number)

ALL INVOLVED	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

Vehicle #1 was backing out of a marked parking space in the parking lot of Laurelton Village (475 Jack Martin Blvd). Vehicle #2 was traveling North bound in the parking lot of Laurelton Village, in the area of Vehicle #1.

Vehicle #1 failed to observe Vehicle #2 and backed up directly into the passenger side of the vehicle. There was minor damage to both vehicles and no injuries were reported.

The driver of Vehicle #1 stated that she did not see Vehicle #2 at all as the vehicle traveling through the lane in the parking lot. The driver of Vehicle #2 stated that he observed that Vehicle #1 was backing as his vehicle passed the vehicle. He stated that he didn't have enough time to avoid the collision.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police Case No: 2016-00053007

