

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police** Case No: **2016-00051479**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Vehicle 1 was east bound on Jack Martin Boulevard when a deer ran from the north side of the road to the south side. Driver 1 stated he did not have time to react causing him to strike the deer with the center of the hood of his vehicle causing the deer to rollover the top of the vehicle.

The only damage observed on Vehicle 1 was a dent on the center of the hood.

No injuries were reported on scene.

Vehicle 1 was driven from the scene.

An animal shelter responded to the scene and took possession of the deer.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram



Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police

Case No: 2016-00051479

Jack
Martin
Boulevard

Quadara Bouevard



P.O.I.

