

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: _____ Case No: **2016-00043799**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Hit and Run crash occurred in the parking lot of Home Depot, located at 1722 RT 88, on 07/11/16.

The owner of vehicle #2, Frank Urso, advised he parked in the parking lot of Home Depot sometime between 1830 and 1930 hrs. on 07/11/16. He stated he was in a handicapped space across from the construction entrance. He was in the store for about a half an hour and then left. He recently just observed damage to the rear tailgate of his vehicle as well as damage to the rear passenger side taillight.

Investigation revealed some evidence, possibly wood fragments, on the taillight itself which would indicate someone backed out of a parking space with a load of wood sticking out of their vehicle. That wood struck the rear of vehicle #2 causing the damage. There does not appear to be any vehicle contact between the hit and run vehicle and vehicle #2.


There is no information about vehicle #1 or its driver.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: _____ Case No: **2016-00043799**



Home Depot
1722 RT 88

