

96	Page 1 of 3		Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report									
05	1 Case Number		2016-00045479										10 Crash Occurred On: Rt. 88		11 Speed Limit		8 8		12 Route No.		13 Milepost		148a					
01	2 Police Dept of		Brick Township										Code: 01		At Intersection with		Road Name		Dir		18 Speed Limit		148b					
01	3 Station/Precinct		Brick Police										300.00		Feet		N E of: Van Zile RD		17 Cross Road Name		3 5		---					
02	4 Date of Crash		mm		dd		yy		5 Day of Week		Su M Tu W Th F Sa		6 Time (use 2400 hrs)		1 2 1 6		7 Municipality Code		1506		119a							
01	23 Veh No		01		24 Policy No.		083 8094-E11 30		25 Ins Code		962		53 Veh No		54 Policy No.		4264-04-68-73		55 Ins Code		148		119b					
01	26 Driver's First Name		Initial		Last Name		Amanda D Amorgretti		29 Sex		F		56 Driver's First Name		Initial		Last Name		Katie L Sotak		59 Sex		01					
01	27 Number and Street		1190 ROUTE 70 W B08		30 Eyes		Brown		57 Number and Street		353 EASTERN BLVD		60 Eyes										01					
02	28 City		BRICK		State		NJ		Zip		08724		58 City		BAYVILLE		State		NJ		Zip		08721					
03	31 State		NJ		32 Drivers License No		A5810 03664 52972		33 DOB		mm dd yy		02 28 97		34 Expires		mm yy		02 18		61 State		62 Drivers License No		S6757 42873 55902			
03	35 Owner's First Name		Initial		Last Name		John Schumatti		65 Owner's First Name		Initial		Last Name		Katie L Sotak		63 DOB		mm dd yy		05 15 90		64 Expires		mm yy		05 19	
03	36 Number and Street		1190 ROUTE 70 W B08		66 Number and Street		353 EASTERN BLVD		67 City		BAYVILLE		State		NJ		Zip		08721		70 Color		Silver		71 Year		2012	
03	37 City		BRICK		State		NJ		Zip		08724		68 Make		Chevrolet		69 Model		Cruze		72 Plate No.		M88BZZ		73 State		NJ	
01	38 Make		TOYOTA		39 Model		Camry		40 Color		White		41 Year		2013		42 Plate No.		L94FBU		43 State		NJ		74 VIN		1G1PC5SH2C7304585	
01	44 VIN		4T4BF1FK7DR294874		45 Expires		05 17		46 Vehicle Removed To		Tow Company Lot		47 Authority		Owner Driver Police		76 Vehicle Removed To		Driven Away		77 Authority		Owner Driver Police		75 Expires		03 17	
01	48 Alcohol/Drug Test		Given: No Yes Refused		Type: Breath Blood Urine		Results: 0 % Pending		49 Hazardous Material		Name or Placard No.		50 Carrier No.		USDOT Other *		78 Alcohol/Drug Test		Given: No Yes Refused		Type: Breath Blood Urine		Results: 0 % Pending		79 Hazardous Material		Name or Placard No.	
01	51 Commercial Vehicle Weight		≤ 10,000 lbs		10,001 - 26,000 lbs		≥ 26,001 lbs		52 Carrier name				80 Carrier No.		USDOT Other *		81 Commercial Vehicle Weight		≤ 10,000 lbs		10,001 - 26,000 lbs		≥ 26,001 lbs		82 Carrier name			
03	53 Damage To Other Property		None		134 Crash Diagram (NOT TO SCALE)				135 Damage To Other Property		None		136 Damage To Other Property		None		137 Charge		39:4-97		138 Summons No.		E16-4541		139 Charge		Multiple Charges	
04	141 Officer's Signature		Austin Kenny		142 Badge No.		224		143 Reviewed By		Cook		144 Case Status		Pending Complete		145 Case Status		Pending Complete		146 Case Status		Pending Complete		147 Case Status		Pending Complete	
A	83		84		85		86		87		88		89		90		91		92		93		94		95		Names & Addresses of Occupants - If Deceased, Date & Time of Death	
B	1		01		01		--		19		F		--		--		--		09		04		--		--		Amanda D Amorgretti 1190 ROUTE 70 W B08 BRICK, NJ 08724	
C	2		01		01		--		26		F		--		--		--		09		04		--		--		Katie L Sotak 353 EASTERN BLVD BAYVILLE, NJ 08721	
D																												
E																												

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00045479**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Vehicle 1 was exiting Laurel Square onto Rt. 88 West, making a right turn. Vehicle 2 was traveling West on Rt. 88. Vehicle 1 and vehicle 2 collided on Rt. 88.

Driver 2 stated that she was going straight ahead and vehicle 1 turned out in front of her. Driver 2 stated that she thought vehicle 1 was turning left but was not sure. Driver 2 stated that she swerved to the left to avoid collision but was unable to.

Driver 1 stated that she was turning right onto Rt. 88, exiting the parking lot. She stated that driver 2 was possibly using a cellular phone. Driver 2 denied using a cellular phone.

Debris from the crash, likely the point of impact, was on the center line, in front of the exit, slightly West.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: **Brick Police**

Case No: **2016-00045479**

Van Zile Rd

ROUTE 88

