

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police** Case No: **2016-00038841**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

Vehicle #2 was traveling east on Route 88 approaching Olden Avenue. Vehicle #1 was attempting to exit the Oxford Plaza, 1715 Route 88, and make a right turn onto Route 88 eastbound. Vehicle #1 exited the plaza and failed to yield to Vehicle #2. Vehicle #1 entered the roadway in Vehicle #2's path. Vehicle #2 struck Vehicle #1 as Vehicle #1 entered the roadway.

Driver #2 complained of chest pain from the air bag deployment. Driver #2 was transported to Brick Hospital by Brick PD EMS.

I issued Driver #1 a summons for Careless Driving (summons # E16-003877).

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police

Case No: 2016-00038841

