

NJ Accident Report 2016-00039666 Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00039666**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Vehicle 2 stopped in traffic on Route 88 eastbound just prior to intersection with Coolidge Drive. Vehicle 1 traveling eastbound on Route 88 directly behind Vehicle 2.

Driver of Vehicle 1 stated they were unable to stop in time and crashed into the rear of Vehicle 2.

Driver of Vehicle 2 stated they were at a stop in traffic when Vehicle 1 crashed into them from behind.

Based on my investigation and observations on scene I determined Vehicle 1 to be at fault for the motor vehicle crash.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police Case No: 2016-00039666

