

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police** Case No: **2016-00039919**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

Vehicle 2 traveling eastbound on Route 88 just prior to intersection with Midstreams Road. Vehicle 1 traveling directly behind Vehicle 2 on Route 88.

Driver of Vehicle 1 stated that Vehicle 2 began to slow down in front of him and he was too close to stop in time. Driver of Vehicle 1 attempted to swerve away to avoid a collision but was unable to. Vehicle 1 crashed into Vehicle 2.

Driver of Vehicle 2 stated that they were slowing down in traffic when they were struck from behind by Vehicle 1.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: **Brick Police**

Case No: **2016-00039919**

