

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00030787**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
L														
I														
N														
V														
O														
L														
V														
E														

135 Crash Description

Vehicle 2 was traveling west on Rt. 70 in the right lane of travel. As Vehicle 2 entered in to the intersection of Rt. 70 and Jack Martin Blvd, it collided with Vehicle 1. Vehicle 2's front portion of the Vehicle collided with the right middle portion of Vehicle 1.

Vehicle 1 was traveling south on Jack Martin Blvd. Vehicle 2 entered the intersection of Jack Martin Blvd and Rt. 70. As Vehicle 1 was approximately three quarters of the way into the intersection it collided with Vehicle 2.

Driver 2 stated he was in the far right lane of travel to go into the jug handle. As he entered into the intersection of Rt. 70 and Jack Martin Blvd, Vehicle 1 entered into the intersection in front of his vehicle. Driver 2 stated he was unable to stop due to him seeing Vehicle 1 last minute.

Driver 1 stated she was traveling east on Rt. 70. She went around the jug handle to travel south on Jack Martin Blvd. Driver 1 stated she stopped at the red traffic signal at the intersection of Jack Martin Blvd and Rt. 70. Driver 1 stated when the traffic light turned green she proceeded into the intersection and Vehicle 2 struck her in the right middle of her vehicle.

Both vehicle's were towed from the scene. Driver 1 was transported to Ocean Medical Center by Brick Police EMS.

Upon conclusion of my investigation, I am un able to determine who is at fault for the crash. Both Driver 1 and Driver 2 are stating that the other party ran the red traffic signal. There were no witnesses to the crash. The scene revealed skid marks approximately 10 feet long, prior to the impact location which Vehicle 1 was traveling.

Vehicle 1 * 24 Self Insured number 79.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: **Brick Police**

Case No: **2016-00030787**

