

NJTR-1 (Rev. 01/17)

New Jersey Police												Case Number			Page <u>2</u> of <u>3</u>		
Crash Investigation Report												2022-00031416					
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

A 2 car motor vehicle crash occurred in the parking lot of 1893 Route 88. There were no reported injuries.

My investigation revealed that vehicle 2 was waiting at the stop sign in the parking lot to turn onto Barb Lane when vehicle 1 backed out of a parking spot and impacted vehicle 2. Driver 1 caused the crash due to unsafe backing and driver inattention.

Driver 1 stated they were backing out of the parking spot and struck vehicle 2.

Driver 2 stated that they were waiting for traffic to clear before leaving the parking lot when vehicle 1 backed into them.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Jeffrey Kenneth Maehl	310	Glenn C Turner	178	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police

Code: 01


Station:

Case No: 2022-00031416

144 Crash Diagram (NOT TO SCALE)



Not To Scale



1893 Route 88

Jeffrey Kenneth Maehl

Officer's Signature

310

Badge Number