

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00024035**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Vehicle 1 was traveling behind Vehicle 2 heading west on Rt 88. Vehicle 2 slowed down to make a legal left turn into the parking lot of 711. The crash occurred when vehicle 1 crashed into the rear of vehicle 2.

Vehicle 1's driver stated he did not see Vehicle 2's blinker or brake lights due to sun glare. Vehicle 2's driver stated he was coming to a complete stop to wait to make the left turn when Vehicle 1 crashed into the rear of him.

No injuries were reported on scene.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: **Brick Police**

Case No: **2016-00024035**

