

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00024617**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

The driver of vehicle #1 stated she was backing out of a parking space at 1929 Rt. 88. She stated she failed to observe vehicle #2 parked directly behind her. She stated that as she backed up, her bumper rubbed the front driver side panel of vehicle #2.

The driver of vehicle #2 stated she was out of her vehicle, delivering a package to a business. She stated her vehicle was turned off and parked, unoccupied. She stated vehicle #1 struck her vehicle while backing up. No injuries reported. Minor damage to both vehicles.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: **Brick Police**

Case No: **2016-00024617**

Rt.
88

Parking lot of
2919 Rt. 88

2

1