

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00024709**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Vehicle 1 was traveling east on Route 88 just past Park Avenue. Vehicle 1 ran off the right side of the road and struck a utility pole with the front passenger side. The pole was next to the mailbox for 1477 Route 88. Vehicle 1 made a left turn onto Clay Avenue and the driver of vehicle 1 attempted to change his tire. The crash was called in by a witness.

The driver of Vehicle 1 stated he knew he struck the pole, but just wanted to move his vehicle, so he could change the tire. The driver also advised Ptl. Vendrell that he was using his cell phone while driving.

The driver of Vehicle 1 appeared to be under the influence. Ptl. Vendrell conducted field sobriety tests and subsequently took the driver of Vehicle 1 into custody. See his report for further details.

The pole number that was struck was JC134BK and it was damaged. An employee from JCP&L responded to check the utility pole.

The driver of vehicle 1 was issued the following summonses by Ptl. Vendrell:

39:4-50 E16002509
 39:4-97 E16002510
 39:4-96 E16002511
 39:4-129B E16002512

New Jersey Police Crash Investigation Report


Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: **Brick Police**

Case No: **2016-00024709**

Route 88



V1



Pole # JC134BK

V1

