

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00026201**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Vehicle #2 was merging onto Route 70 westbound from Route 88 eastbound and Vehicle #1 was directly behind Vehicle #1. Vehicle #2 slowed down for the yield sign before merging onto Route 70 westbound and as she began to accelerate into the roadway, Vehicle #1 struck the left rear bumper of Vehicle #2 with the right front of Vehicle #1. Vehicle #1 did not stop at the scene and continued westbound on Route 70. Driver #2 described Vehicle #1 as a blue car with partial NJ registration G2WKK, being occupied by two younger white males. Vehicle #2 received minor paint damage to the left side of the bumper.

New Jersey Police Crash Investigation Report


Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**


Station: **Brick Police**

Case No: **2016-00026201**

NOT TO SCALE



Ramp from Route 88



Route 70