

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00021478**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Vehicle 1 was stopped at the stop sign on Burrsville Rd., waiting to make the left turn onto Rt. 88 (east). Vehicle 1 accelerated at an unsafe speed to make the left turn on the wet road surface. Vehicle 1 continued straight, where it struck a curb before crashing into a utility pole, where it came to a final rest. The front of Vehicle 1 was damaged in the crash.


New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: **Brick Police**

Case No: **2016-00021478**



227 DRUM POINT RD