

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: _____ Case No: **2016-00015385**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description


This crash took place in the parking lot of Walmart (1872 Route 88) in the stall of parking spaces marked as "Row #3". Vehicle 2 was parked in a space facing forward along the right side as viewed from the storefront. Vehicle 1 was attempting to park in the space directly to the left of Vehicle 2 and struck Vehicle 2 along the passenger side. Driver 1 reported that he heard a horn sounding causing a distraction while he was parking. No injuries were reported on scene and the owner of Vehicle 2 was located and notified of the crash while on scene. Both vehicles were able to be driven away.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: _____ Case No: **2016-00015385**



ROW #3