

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2022-00043361			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 and Vehicle 2 were traveling west on Route 88 towards Allaire Ave. The front left of Vehicle 1 struck the back right of Vehicle 2 as Vehicle 2 was attempting to make a left turn.

The driver of Vehicle 1 stated that he was too close behind Vehicle 2 when it slowed down to make a turn. He swerved to the right to avoid the collision and struck the back right of Vehicle 2. He was not injured in the crash but his vehicle was disabled.

The driver of Vehicle 2 stated that she was slowing down to make a left turn when her vehicle was struck. She was not injured in the crash and her vehicle suffered moderate damage.

After speaking with both drivers and conducting my investigation, I determined the driver of Vehicle 1 to be at fault for the crash.


146. Officer's Signature Matthew Farnkopf	147. Badge # 314	148. Reviewer —	Badge # —	149. Case Status ☐ Pending ☒ Complete
--	---------------------	--------------------	--------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01


Station: Case No: 2022-00043361

144 Crash Diagram (NOT TO SCALE)



Not To Scale

Route 88



Allaire Ave

Matthew Farnkopf

Officer's Signature

314

Badge Number