

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00010725**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Vehicle #1 was traveling East bound on Route 88, approaching the intersection of Midstreams Road. Vehicle #2 was stopped in traffic, for a red traffic signal on Route 88 at the intersection of Midstreams Road.

The driver of Vehicle #1 failed to stop and struck the rear-end of Vehicle #2. There was damage to both vehicles and no injuries were reported.

The driver of Vehicle #1 stated that she incorrectly believed that the driver of Vehicle #2 was going to proceed through an amber light. The driver of Vehicle #2 stated that she had come to a full stop at the red light when she was rear-ended.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: **Brick Police**

Case No: **2016-00010725**

