

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00010912**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
L														
I														
N														
V														
O														
L														
E														

135 Crash Description

Investigation revealed vehicle 1 rear ended vehicle 2 in the left travel lane of Rt 88 approximately 250 feet east of Rt 70.

Driver vehicle 1 stated he accidentally collided with the rear of vehicle 2 while attempting to stop behind it. Driver vehicle 1 added he struck the trailer hitch and ball of vehicle 2 and did not think he damaged the actual vehicle. Driver vehicle 2 stated she was stopped in traffic at the red signal on Rt 88 when she was struck from behind by vehicle 1. Driver vehicle 2 stated she is four months pregnant and the force of the crash caused pain and discomfort to her stomach. Driver vehicle 2 refused treatment from Brick Police EMS on scene. Driver vehicle 2 responded to Brick ER with family members who responded to the scene.

I observed vehicle 1 to have damage to the front hood. The damage matched the height and shape of the trailer hitch and ball from vehicle 2.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police

Case No: 2016-00010912

