

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police** Case No: **2016-00007084**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

Vehicle #02 was traveling eastbound on Route 88 and stopped behind and unknown vehicle which was stopped for traffic while attempting to make a left turn onto Clay Ave. Vehicle #01 traveling eastbound on Route 88 and approaching vehicle #02 from the rear. Driver of vehicle #01 stated that he attempted to stop behind vehicle #02 but failed to do so in time, causing his vehicle to rear end vehicle #02. The plow attached to the front of vehicle #01 struck the rear bumper of vehicle #02, causing a collision.

Vehicles were moved prior to police arrival. No injuries were reported at the scene. Passenger of vehicle #02 was gone prior to police arrival but driver of vehicle #02 provided his information and advised that he was not injured during the accident.

*Driver of vehicle #01's insurance info:

Zurich American Insurance Company #NAIC 16535
1400 American Lane
Schaumburg, IL 60196

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police

Case No: 2016-00007084



Clay Ave.

Route 88

