

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00011429**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

Vehicle 2 parked legally and unoccupied in parking spot in parking lot of the Walmart located at 1872 Route 88.

Vehicle 1 pulls into parking spot directly in front of Vehicle 2. Vehicle 1 pulls into spot too far and crashes into Vehicle 2. Driver of Vehicle 1 stated she was unaware she had crashed into Vehicle 2 until she exited the vehicle and observed her vehicle past the line for her parking spot and the contact between both vehicles.

Based on my investigation and observations on scene I determined Vehicle 1 to be at fault for the motor vehicle crash.



New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police Case No: 2016-00011429

Walmart
1872 Route 88



Parking Lot

