

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: _____ Case No: **2016-00012496**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Vehicle 1 a black GMC Terrain, NJ H28FVP was traveling westbound on Highway 88 crossing through the intersection of Van Zile Rd. Driver of Vehicle 1 stated an unknown make or model of vehicle crossed over into his lane forcing Vehicle 1 to swerve to the right. Vehicle 1 then struck the curb and light signal station causing damage to the front of Vehicle 1.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: _____ Case No: 2016-00012496

