

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police** Case No: **2016-00012641**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

Vehicle 2 was struck from behind by vehicle 1 while stopped in the driveway of Brick Hospital while waiting to enter Rt. 88 west bound. Driver 1 stated that while stopped behind vehicle 2 waiting to enter Rt. 88, she observed vehicle 2 begin to move forward to enter Rt. 88. Believing vehicle 2 was proceeding onto Rt. 88, she took her eyes off vehicle 2 and looked east for approaching traffic. As she moved forward, she collided with vehicle 2 who had not yet entered the roadway. Driver 2 stated that she had initially moved forward but stopped for approaching vehicles and once stopped, was struck from behind. No injuries were reported at this time and only minor damage was observed to both vehicles.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police

Case No: 2016-00012641

