

NJ Accident Report 2016-00007858 Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: _____ Case No: **2016-00007858**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

VEHICLE 1 WAS TRAVELING WEST ON RT 88 WEST IN THE FAR LEFT LANE, APPROACHING THE INTERSECTION OF RT 70. VEHICLE 2 WAS ALSO TRAVELING ON RT 88 WEST IN THE LEFT LANE APPROACHING THE INTERSECTION OF RT 70 DIRECTLY BEHIND VEHICLE 1.

AS BOTH CARS TRAVELED THROUGH THE INTERSECTION, VEHICLE 1 STOPPED ABRUPTLY, CAUSING VEHICLE 2 TO COLLIDE WITH THE REAR OF VEHICLE 1.

THE DRIVER OF VEHICLE 1 STATED AS HE TRAVELED THROUGH THE INTERSECTION OF RT 88 WEST AND RT 70, AS THE LIGHT HAD TURNED RED HE DECIDED TO STOP. HE WAS UNSURE WHERE EXACTLY THE COLLISION OCCURRED AND THOUGHT IT MIGHT HAVE BEEN BEFORE THE CROSSWALK.

THE DRIVER OF VEHICLE 2 STATED HE WAS TRAVELING DIRECTLY BEHIND VEHICLE 1 ON RT 88 WEST APPROACHING RT 70. BOTH VEHICLES BEGAN TO TRAVEL THROUGH THE INTERSECTION AS THE LIGHT TURNED RED AND VEHICLE 1 STOPPED OUT OF NO WHERE, CAUSING HIS VEHICLE TO COLLIDE WITH VEHICLE 1.

THERE WERE NO REPORTED INJURIES AT THE SCENE, AND THERE WAS DAMAGE TO THE REAR OF VEHICLE 1 AND THE FRONT OF VEHICLE 2.

INVESTIGATION AT THE SCENE SHOWED DEBRIS WAS IN THE ROADWAY, APPROXIMATELY 30-50 FEET PASSED THE CROSSWALK ON RT 88. WHICH INDICATED THE COLLISION OCCURRED AS THE TWO VEHICLES TRAVELED THROUGH THE INTERSECTION OF RT 70 BEFORE VEHICLE 1 DECIDED TO STOP.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: _____ Case No: 2016-00007858

