

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00008937**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

Vehicle #03 had utilized the U-Turn from Route 70 eastbound towards Olden St and was stopped at a red traffic signal on Olden St in the right lane. Vehicle #02 was stopped directly behind vehicle #03. Vehicle #01 had negotiated the U-Turn and was approaching vehicle #02 from the rear. Driver of vehicle #02 stated as she was stopped at the red traffic signal, vehicle #01 rear ended her as the traffic signal was still red. Driver of vehicle #01 stated he thought the traffic signal was green and began to slow down as he approached the vehicles from behind, but could not stop in time causing him to rear end vehicle #02. The front bumper of vehicle #01 struck the rear bumper of vehicle #02. The force of impact caused vehicle #02 to proceed forward and rear end vehicle #03. The front bumper of vehicle #02 struck the rear bumper of vehicle #03 causing a second collision.

All vehicles were moved prior to police arrival. Driver of vehicle #02 advised she had spoken to the driver of vehicle #03 and due to no visible damage caused from the second accident, driver of vehicle #03 did not wish a police report and left prior to police arrival. Driver of vehicle #02 indicated there was no visible damage to the front of her vehicle either caused from the second accident so she did not obtain any information from driver of vehicle #03. Driver of vehicle #02 stated vehicle #03 was a small maroon sedan driven by an elder white female.

Driver of vehicle #02 had complaint of pain to the back of her head caused from being rear ended by vehicle #01 but she did not wish for medical attention. No other injuries were reported at the scene. Vehicle #02 sustained damaged to the rear of her vehicle and vehicle #01 sustained damage to the front of his vehicle due to the initial accident.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: **Brick Police**

Case No: **2016-00008937**

Olden Street

NOT TO SCALE



Highway 70

