

Page <u>1</u> of <u>3</u> ☐ Fatal New Jersey Police Crash Investigation Report ☒ Reportable ☐ Non-Reportable ☐ Change Report														
96 04	1 Case Number 2015-00073429	10 Crash Occurred On: 1930 Route 88	11 Speed Limit 8 8	118a 02										
97 01	2 Police Dept of Brick Township	Code 01	12 Route No. Suffix 13 Milepost 18 Speed Limit	118b 04										
98 01	3 Station/Precinct Brick Police	4 Date of Crash 1 2 0 5 1 5	5 Day of Week Su M Tu W Th F Sa	119a 25										
99 09	6 Time (use 2400 hrs) 1 5 4 7	7 Municipality Code 1506	8 Total Killed 9 Total Injured	119b ---										
100 01	23 Veh No 01	24 Policy No. 033292708671016	25 Ins Code 200	120 01										
101 02	26 Driver's First Name Rosemary Naughton	29 Sex F	56 Driver's First Name Joseph A Polichemi	121 01										
102 01	27 Number and Street 229 Martool DR	30 Eyes Blue	57 Number and Street 49 Grand Teton AVE	122 ---										
103 01	28 City Woodbridge	State NJ	Zip 07095	123 ---										
104 02	31 State NJ	32 Drivers License No N 0 8 7 9 6 7 1 6 1 5 5 4 7 4	33 DOB 0 5 1 3 4 7	124 03										
105 02	34 Expires 0 5 1 8	61 State NJ	62 Drivers License No P 6 2 5 7 4 1 0 6 1 1 0 5 9 5	125 01										
106 ---	35 Owner's First Name Rosemary Naughton	65 Owner's First Name Joseph A Polichemi	63 DOB 1 0 2 3 5 9	126 11										
107 ---	36 Number and Street 229 Martool DR	66 Number and Street 49 Grand Teton AVE	64 Expires 1 1 1 7	127 11										
108 01	37 City Woodbridge	State NJ	Zip 07095	128a 26										
109 01	38 Make NISSAN	39 Model Altima	40 Color Black	128b ---										
110 01	41 Year 2013	42 Plate No. R70CUJ	43 State NJ	128c ---										
111 01	44 VIN 1N4AL3AP8DN487441	45 Expires 01 17	74 VIN 4A3AB56F68E024645	128d ---										
112 ---	46 Vehicle Removed To Driven Away	47 Authority ☒ Owner ☒ Driver ☐ Police	75 Expires 04 16	129a 26										
113 ---	48 Alcohol/Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0.____% ☐ Pending	78 Alcohol/Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0.____% ☐ Pending	79 Hazardous Material On Board Spill ☐ ☐ ☐	129b ---										
114 ---	49 Hazardous Material On Board Spill ☐ ☐ ☐	77 Authority ☒ Owner ☒ Driver ☐ Police	80 Carrier No. ☐ USDOT ☐ Other *	129c ---										
115 ---	50 Carrier No. ☐ USDOT ☐ Other *	81 Commercial Vehicle Weight ☐ ≤ 10,000 lbs ☐ 10,001 - 26,000 lbs ☐ ≥ 26,001 lbs	82 Carrier name	129d ---										
116 04	51 Commercial Vehicle Weight ☐ ≤ 10,000 lbs ☐ 10,001 - 26,000 lbs ☐ ≥ 26,001 lbs	134 Crash Diagram (NOT TO SCALE)		130 02										
117 01	52 Carrier name			131 02										
136 Damage To Other Property None														
Oper. 1	137 Charge ☐ Multiple Charges	138 Summons No.	Oper. 2	139 Charge ☐ Multiple Charges										
141 Officer's Signature Ryan Wynn		142 Badge No. 261	143 Reviewed By Badge No. 144 Case Status ☐ Pending ☐ Complete											
A	83 1	84 01	85 01	86 --	87 68	88 F	89 --	90 --	91 --	92 09	93 04	94 --	95 --	Names & Addresses of Occupants - If Deceased, Date & Time of Death Rosemary Naughton 229 Martool DR Woodbridge, NJ 07095
B	83 2	84 01	85 01	86 --	87 56	88 M	89 --	90 --	91 --	92 09	93 04	94 --	95 --	Joseph A Polichemi 49 Grand Teton AVE Howell, NJ 07731
C														
D														
E														

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2015-00073429**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

Investigation at the scene indicated the following: Vehicle 2 traveled south towards Route 88 in the parking lot of 1930 Route 88 near Provident Bank. Vehicle 1 was also in the parking lot of 1930 Route 88 and attempted to turn left to travel south towards Route 88. As vehicle 2 traveled passed vehicle 1, vehicle 1 turned left and struck the rear driver side door of vehicle 2 with the front right of the vehicle.

Driver 1 stated she was in the parking lot of 1930 Route 88 and turned left to travel south towards Route 88. Driver 1 stated while she traveled south, vehicle 2 tried to pass her and struck the side of her vehicle. Driver 1 stated she looked both ways and did not observe any vehicles before she turned left to travel towards Route 88.

Driver 2 stated he traveled south towards Route 88 in the parking lot of 1930 Route 88. Driver 2 stated as he traveled south in the parking lot, he observed vehicle 1 on the driver side of his vehicle from his peripherals and the rear driver side door was suddenly struck by the front of vehicle 1.

There were no reported injuries at the time of the incident and moderate damages to both vehicles.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police

Case No: 2015-00073429

