

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2022-00051282			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

V1 and V2 were on Rt 88 eastbound, utilizing the ramp to merge towards Rt 70 westbound.

D1 alleges that he believed that V2 had merged and as D1 was attempting to monitor traffic for an opening V1 struck V2.

D2 alleges that he was attempting to merge onto Rt 70. He believed he had ample time to merge and began to move, but ultimately stopped to yield for on-coming traffic. V1 struck V2 in the rear.

As a result of my investigation, I found V1 to be at fault for the MVC.

146. Officer's Signature Peter Allen Bylsma	147. Badge # 328	148. Reviewer Joseph T Pacitti	Badge # 238	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01

Station:


Case No: 2022-00051282

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



NOT TO SCALE



Peter Allen Bylsma

Officer's Signature

328

Badge Number