

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2022-00052030			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

A motor vehicle crash occurred in the area of Laurel Square (1930 Route 88).

Driver of Vehicle #1 advised she was traveling east on Route 70. Driver #1 advised she turned right into Laurel Square, but was going too fast and struck the curbed median and then the concrete support for light pole #27.

There was disabling damage to the front driver side tire of Vehicle #1. There was minor paint transfer off the concrete support.

Vehicle #1 was towed by Andrew's Auto Body.

Vehicle #1 attempted to turn into Laurel Square, but was going too fast for the turn. Vehicle #1 struck the curbed median and traveled on the median into the concrete support for light pole #27. Driver #1 is the at fault driver for unsafe speed and driver inattention.

Driver #1 was issued the following summons: 1506 E22 003331 for 39:4-97, careless driving.

146. Officer's Signature Brian R Foley	147. Badge # 247	148. Reviewer Jason R Shepherd	Badge # 167	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01

Station:


Case No: 2022-00052030

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Not To Scale



Brian R Foley

Officer's Signature

247

Badge Number