

96	Page 1 of 3		☐ Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report		118a								
05	1. Case Number		2022-00057033										10. Crash Occurred On:		MIDSTREAMS RD		11. Speed Limit		3 5		09								
97	2. Police Dept. of		Brick Police										Code		01		12. Route No.		Suffix		118b								
01	3. Station/Precinct												75		14		15		16		25								
98	4. Date of Crash		mm		dd		yy		5. Day of Week		Su M Tu W Th F Sa		6. Time (use 2400 hrs.)		1 9 0 2		7. Municipality Code		1 5 0 6		119a								
01	8. Total Killed		-		-		9. Total Injured		-		-		19. To:		17. Cross Road Name/Route No.		18. Speed Limit		3 5		119b								
07	23. Veh. #		935471502										25. NJ Ins. Code		134		53. Veh. #		F070828-9										119c
100a	24. Policy No.												54. Policy No.												120a				
01	26. Driver's First Name		Connor										Initial		J		Last Name		Reynolds										120b
04	27. Number & Street		2035 BEACH BLVD										28. City		Pt. Pleasant Boro										121a				
02	29. Sex		M										56. Driver's First Name		Carolyn										121b				
01	30. Eyes		0 2										DL Class		D										122				
01	31. State		NJ										60. Eyes		0 4										123				
02	32. Driver's License Number		R 2 9 8 8 1 3 4 7 1 0 7 0 5 2										33. DOB		0 7 1 2 0 5										124				
01	34. Expires		0 7 2 6										62. Driver's License Number		L 6 1 0 8 1 1 3 6 1 5 7 6 4 4										125				
01	35. Owner's First Name		Alexis D Gass										Initial				Last Name		Carolyn A Loehwing										126
01	36. Number & Street		2035 BEACH BLVD										37. City		Pt. Pleasant Boro										126a				
01	38. Make		Mazda										39. Model		Mazda 6										126b				
04	40. Color		BL										41. Year		2015										126c				
01	42. Plate No.		R26MCF										43. State		NJ										126d				
01	44. VIN		J M 1 G J 1 U 5 3 F 1 1 8 0 3 7 4										45. Expires		01/23										126e				
01	46. Vehicle Removed to:		☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded ☐ Left at Scene ☐ Towed Impounded										76. Vehicle Removed to:		☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded ☐ Left at Scene ☐ Towed Impounded										127a				
01	47. Authority		☐ Owner ☒ Driver ☐ Police										77. Authority		☐ Owner ☒ Driver ☐ Police										127b				
01	48. Alcohol Drug Test		Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0.00 % ☐ Pending										49. Hazardous Material		☒ None ☐ On Board ☐ Spill										127c				
01	50. Carrier No.		☐ USDOT ☒ None										51. GVWR / GCWR (trucks & buses only)		☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.										127d				
01	52. Motor Carrier or Government Entity												82. Motor Carrier or Government Entity												127e				
01	53. Number & Street												83. Number & Street												128				
01	54. City												84. City												129				
01	55. State												85. State												130				
01	56. Zip												86. Zip												131				
01	135. Damage to Other Property		☐ Yes (If Yes, describe) ☒ No										137. Summons No.												132				
01	136. Charge												138. Charge												133				
01	139. Summons No.												140. Charge												134				
01	141. Summons No.												142. Charge												02				
Names & Addresses of Occupants If Deceased, Date & Time of Death																													
A 01 01 17 M 11 04 Connor J Reynolds 2035 BEACH BLVD Pt. Pleasant Boro NJ 08742																													
B 01 02 16 M 11 04 Michael F Mucardo 3801 HERBERTSVILLE RD B Pt. Pleasant Boro NJ 08742																													
C 02 01 58 F 11 04 Carolyn A Loehwing 859 ARNOLD AVE apt 12 Pt. Pleasant Boro NJ 08742																													
D																													

New Jersey Police Crash Investigation Report												Case Number 2022-00057033			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On scene investigation revealed that vehicle 1 was traveling northbound on Midstreams Rd. Vehicle 2 was stopped in traffic approximately 75 feet from Rt 88. Vehicle 1 failed to stop and struck vehicle 2. The drivers provided the following statements:

Driver 1 stated he was driving north on Midstreams Rd as he was approaching Rt. 88. he had attempted to slow down and stated his car had stalled resulting in him colliding with vehicle 2. Vehicle 1 showed no visible damage and was driven from the scene. Neither driver 1 nor the front seat passenger had reported injuries on scene.

Driver 2 stated that she was stopped at the light on Midstreams Rd. just before Rt. 88 waiting to make the right turn when she was struck by vehicle 1. Vehicle 2 had minor scratches to the rear bumper and was driven from the scene. Driver 1 did not report any injuries on scene.

Investigation concluded that vehicle 1's actions were responsible for the collision and driver 1 was found to be at fault. See diagram for further details. Body camera activated during investigation.

146. Officer's Signature Glen Pacyna	147. Badge # 287	148. Reviewer —	Badge # —	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------	--------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police

Code: 01

Station:

Case No: 2022-00057033

144 Crash Diagram (NOT TO SCALE)



Glen Pacyna

Officer's Signature

287

Badge Number