

New Jersey Police Crash Investigation Report													Case Number 2022-00058255		Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E	02	04	01	—	00	F	—	—	—	06	06	—	—	Gemma Velsquez-Lopez 1267 W WHEAT RD VINELAND NJ 08360		
F	02	06	01	—	08	M	05	08	01	04	11	—	—	Juan Reymundo-Lopez 1267 W WHEAT RD VINELAND NJ 08360		
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was traveling (eastbound) on Rt. 70 in the right lane. Vehicle 1 was traveling on Rt. 70 in the right lane behind Vehicle 2. Vehicle 1 then struck Vehicle 2 in the rear. Vehicle 1 received minor damage to the front panel. Vehicle 2 received minor damage to the rear panel.

Driver of Vehicle 1 stated he was traveling behind Vehicle 2 on Rt. 70. Driver 1 stated he believed he dosed off for a second due to lack of sleep. Driver 1 stated he tapped Vehicle 2 in the rear and the accident was his fault.

Driver of Vehicle 2 stated she was traveling on Rt. 70 in the right lane. Driver 2 stated Vehicle 1 then struck her in the rear.

From my investigation, I find Driver of Vehicle 1 at fault for the crash.

146. Officer's Signature Turner Allen Robbins	147. Badge # 311	148. Reviewer Henry J Drew	Badge # 147	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2022-00058255

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Turner Allen Robbins

311