

New Jersey Police Crash Investigation Report												Case Number 2022-00061528			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 01 was traveling south on Jack Martin Rd making at right turn at the intersection of Rt 70 West crossing over to the left lane when struck by Vehicle 02 traveling west on Rt 70 in the rear.

Driver of Vehicle 01 stated she was traveling south on Jack Martin Blvd. when she made a right on red and crossed over to the Left lane. Driver of Vehicle 01 stated the left lane was clear when her vehicle was struck in the rear by Vehicle 02.

Driver of Vehicle 02 stated that he was traveling west on Rt 70 when Vehicle 01 made a right turn from Jack Martin Blvd immediately crossed over to left lane in front of him at a slow speed. Driver of Vehicle 02 stated he couldn't stop in time striking Vehicle 01.

Vehicle 02 was towing a trailer (NJ REG TYS68L) with a tractor on it.

Driver of Vehicle 01 admitted fault with the improper lane change when making a right turn.


146. Officer's Signature Robert Koch	147. Badge # 170	148. Reviewer John D Gordon	Badge # 237	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2022-00061528

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Robert Koch

Officer's Signature

170

Badge Number