

Page 1 of 3		☐ Fatal		New Jersey Police Crash Investigation Report		☒ Reportable		☐ Non-Reportable		☐ Change Report				
1 Case Number 2015-00077610		10 Crash Occurred On: 1872 Rte 88		11 Speed Limit 1 5						118a 02				
2 Police Dept of Brick Township		Code 01		Road Name		Dir		12 Route No.		13 Milepost				
3 Station/Precinct Brick Police				☐ At Intersection with ☐ Feet ☐ Miles		☐ N ☐ E ☐ S ☐ W of:		17 Cross Road Name		18 Speed Limit				
4 Date of Crash mm dd yy 1 2 2 9 1 5		5 Day of Week Su M Tu W Th F Sa Tu		6 Time (use 2400 hrs) 0 0 0 0		7 Municipality Code 1506		8 Total Killed 0		9 Total Injured 0				
23 Veh No 01		24 Policy No. F2721801		25 Ins Code 426		53 Veh No 2		54 Policy No. 0651834E0430A		55 Ins Code 962				
26 Driver's First Name Marielle A Spero		Initial		Last Name		29 Sex F		56 Driver's First Name		59 Sex				
27 Number and Street 560 Driscoll DR		State		Zip 08724		30 Eyes Blue		57 Number and Street		60 Eyes				
28 City Brick		State NJ		Zip 08724		58 City		State		Zip				
31 State NJ		32 Drivers License No. S7052 51961 60984		33 DOB mm dd yy 10 13 98		34 Expires mm yy 10 19		61 State		62 Drivers License No.				
35 Owner's First Name Marlene A Paulin		Initial		Last Name		65 Owner's First Name Carmen C Laluz		Initial		Last Name				
36 Number and Street 560 Driscoll DR		State		Zip		66 Number and Street 16 Briar Mills DR		State		Zip				
37 City Brick		State NJ		Zip 08724		67 City Brick		State NJ		Zip 08724				
38 Make HYUNDAI		39 Model Santa Fe		40 Color Blue		41 Year 2004		42 Plate No. H90GAN		43 State NJ				
44 VIN KM8SC13D64U726783		45 Expires 11 16		46 Vehicle Removed To ☒ Driven ☐ Left at Scene ☐ Towed		47 Authority ☒ Owner ☐ Driver ☐ Police		74 VIN 1J8GN28K78W210629		75 Expires 11 16				
48 Alcohol/Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0.____% ☐ Pending		134 Crash Diagram (NOT TO SCALE)		78 Alcohol/Drug Test Given: ☐ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0.____% ☐ Pending		79 Hazardous Material On Board ☐ Spill ☐		80 Carrier No. ☐ USDOT ☐ Other *		81 Commercial Vehicle Weight ☐ ≤ 10,000 lbs ☐ 10,001 - 26,000 lbs ☐ ≥ 26,001 lbs				
49 Hazardous Material On Board ☐ Spill ☐		50 Carrier No. ☐ USDOT ☐ Other *		51 Commercial Vehicle Weight ☐ ≤ 10,000 lbs ☐ 10,001 - 26,000 lbs ☐ ≥ 26,001 lbs		52 Carrier name		82 Carrier name						
136 Damage To Other Property None-N/A														
Oper. 1		137 Charge 39:4-97 39:3-13.8(C)		138 Summons No. E15 954E15 9551 E15 9550		Oper. 2		139 Charge		140 Summons No.				
141 Officer's Signature Thomas Caulfield		142 Badge No. 235		143 Reviewed By Naiduk		Badge No. 195		144 Case Status ☐ Pending ☐ Complete						
Names & Addresses of Occupants - If Deceased, Date & Time of Death														
A	83	84	85	86	87	88	89	90	91	92	93	94	95	Marielle Spero 560 Driscoll DR Brick, NJ 08724
B	1	01	01	--	17	F	--	--	--	09	04	--	--	Zahkei King 170 Sawmill RD Brick, NJ 08724
C	1	04	--	00	17	M	00	00	--	04	00	--	--	Vidal Vukovic 767 Iron Court Brick, NJ 08724
D	2	01	01	--	70	F	--	--	--	09	--	--	--	
E														

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2015-00077610**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Crash investigation reveals a two vehicle collision involving a parked vehicle in the Walmart store parking lot located at 1872 Route 88. Vehicle 2 was parked in a marked handicapped parking spot facing east. As vehicle 2 was parked and the driver of vehicle 2 was sitting in the driver's seat with the engine running, vehicle 1 was backing out of a marked, in the Walmart parking lot, parking spot just north of vehicle 2. As vehicle 1 was backing up traveling south out of the parking space, driver of vehicle 1 stated she didn't see vehicle 2 causing the rear of vehicle 1 struck the right middle side of vehicle 2 causing minor damage to both vehicles. Vehicle 2 had a female subject/registered owner, Carmen Laluz (DOB:09/05/1946), sitting in the front driver's seat at the time of the crash. Following the crash, the two male occupants, who were inside vehicle 1 at the time of the crash, exited vehicle 1 and fled the area on foot. It's unknown at this time why the two passengers ran and/or if they were injured in the crash. Driver of vehicle 1 stated she didn't know why the two male passengers ran out of the vehicle following the crash however, driver of vehicle 1 was able to provide the name's of both male passengers. No injuries were reported and both vehicles were driven from the scene. Driver of vehicle 1 was issued motor vehicle summonses for 39:4-97 (1506-E15-9549), 39:3-13.8(C) (1506-E15-9550), and 39:3-13.8(B) (1506-E15-9551).

New Jersey Police Crash Investigation Report


Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: **Brick Police**

Case No: **2015-00077610**

1872 Route 88



NOT TO SCALE

