

☐ Fatal

New Jersey Police Crash Investigation Report

☒ Reportable☐ Non-Reportable☐ Change Report

Page 1 of 3		Fatal		New Jersey Police Crash Investigation Report		Reportable		Non-Reportable		Change Report	
04	1 Case Number 2015-00049451		10 Crash Occurred On : 1808 RT 88		11 Speed Limit 3 5		12 Route No.		13 Milepost		118a
01	2 Police Dept of NJ0150600		Code 1		Road Name -1 Post RD		14		15		08
98	3 Station/Precinct		200.00		16		17 Cross Road Name		18 Speed Limit		118b
01	4 Date of Crash 08/10/15		5 Day of Week Su		6 Time 1025		7 Municipality 1506		8 Total Killed		119a
02	23 Veh No 01		24 Policy No A07-238-69154B-7055		25 Ins Code 914		53 Veh No 02		54 Policy No PAA80002010734		25
100	26 Driver's First Name JOSEPH		Initial M		29 Sex M		56 Driver's First Name Laura		Initial S		119b
01	27 Number and Street 464 MANTOLOKING RD		28 City BRICK TOWNSHIP		State NJ		Zip 08723		57 Number and Street 624 CARROLL FOX RD		120
02	31 State		32 Drivers License No		33 DOB 04/14/1948		34 Expires 03/19		58 City BRICK TOWNSHIP		01
03	35 Owner's First Name JP Morgan Chase		Initial JP		Last Name Morgan Chase		65 Owner's First Name Laura		Initial S		121
	36 Number and Street PO BOX 901098		37 City Ft. Worth		State TX		Zip 76103		66 Number and Street 624 CARROLL FOX RD		01
	38 Make MAZDA		39 Model MX3		40 Color Blue		41 Year 2015		42 Plate No. Y59FBV		122
	44 VIN JM1BM1T73F1235684		45 Expires 03/19		74 VIN JN1AZ34E93T003177		75 Expires 01/16		68 Make NISSAN		123
	46 Vehicle Removed To Driven Away		47 Authority Owner Driver Police		76 Vehicle Removed To Driven Away		77 Authority Owner Driver Police		69 Model 350Z		124
	48 Alcohol/Drug Test Given : No		Type : Breath		Results : 0.00 %		78 Alcohol/Drug Test Given : No		Type : Breath		03
	49 Hazardous Material On Board		Name or Placard No.		50 Carrier No.		79 Hazardous Material On Board		Name or Placard No.		125
	51 Commercial Vehicle Weight ≤ 10,000 lbs		52 Carrier name		80 Carrier No.		81 Commercial Vehicle Weight ≤ 10,000 lbs		82 Carrier name		01
	135 Crash Description SEE NARRATIVE		136 Damage To Other Property None		137 Charge		138 Summons No.		139 Charge		126
	141 Officer's Signature Robert Koch		142 Badge No. 0170		143 Reviewed By Patrick J Co		144 Case Status Complete		145 Summons No.		05
	83		84		85		86		87		127
	88		89		90		91		92		11
	93		94		95		96		97		128a
	98		99		100		101		102		26
	103		104		105		106		107		128b
	108		109		110		111		112		128c
	113		114		115		116		117		128d
	118		119		120		121		122		129a
	123		124		125		126		127		26
	128		129		130		131		132		129b
	133		134		135		136		137		129c
	138		139		140		141		142		129d
	143		144		145		146		147		130
	148		149		150		151		152		02
	153		154		155		156		157		131
	158		159		160		161		162		02
	163		164		165		166		167		132
	168		169		170		171		172		10
	173		174		175		176		177		133
	178		179		180		181		182		10
	183		184		185		186		187		
	188		189		190		191		192		
	193		194		195		196		197		
	198		199		200		201		202		
	203		204		205		206		207		
	208		209		210		211		212		
	213		214		215		216		217		
	218		219		220		221		222		
	223		224		225		226		227		
	228		229		230		231		232		
	233		234		235		236		237		
	238		239		240		241		242		

New Jersey Police Crash Investigation Report

Police Dept: NJ0150600 Code: 1

Motor Vehicle Crash Description

Station: Case No: 2015-00049451

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	----
B	---	---	---	---	---	---	---	---	---	---	---	---	---	----
C	---	---	---	---	---	---	---	---	---	---	---	---	---	----
D	---	---	---	---	---	---	---	---	---	---	---	---	---	----
E	---	---	---	---	---	---	---	---	---	---	---	---	---	----

135 Crash Description

Vehicle 01 was traveling east in the left lane on Rt 88 making a left turn crossing two lanes of travel striking Vehicle 02 that was traveling west on Rt 88 in the third right lane.

Driver of Vehicle 01 stated he was traveling east in the left lane on Rt 88 and attempted to make a left turn into the 1808 Rt 88 Attorneys office after he was waved clear by another vehicle traveling west on Rt 88 striking Vehicle 02.

Driver of Vehicle 02 stated she was traveling west on Rt 88 in the right lane when Vehicle 01 made a left turn in front of her.

Both Vehicles moved prior to Police arrival.

Vehicle 01 made an Improper left turn over two double yellow traffic lines.

Robert Koch

0170

New Jersey Police Crash Investigation Report

Police Dept: NJ0150600 Code: 1

Motor Vehicle Crash Diagram

Station: _____ Case No: 2015-00049451

134 Crash Diagram (NOT TO SCALE)

 Indicate North

This image shows a full page of blank graph paper. The grid consists of thin, light gray horizontal and vertical lines that intersect to form small squares across the entire surface. There are no margins, text, or other markings on the paper.

Robert Koch

0170