

96	05	Page 1 of 3	☐ Fatal	New Jersey Police Crash Investigation Report										☒ Reportable	☐ Non-Reportable	☐ Change Report				
97	01	1 Case Number 2015-00050334		10 Crash Occurred On: 1887 RT 88										11 Speed Limit		12 Route No.		13 Milepost		118a
98	01	2 Police Dept of NJ0150600		Code 1		☐ At Intersection with ☐ Feet ☐ Miles										Road Name Dir		18 Speed Limit		118b
99	09	3 Station/Precinct		4 Date of Crash mm dd yy		5 Day of Week Su M Tu W Th Fr Sa		6 Time (use 2400 hrs)		7 Municipality Code		8 Total Killed		9 Total Injured		17 Cross Road Name		19 Ramp		119a
100	05	23 Veh No		24 Policy No. PA142105100		25 Ins Code 184		53 Veh No		54 Policy No.		55 Ins Code		21 Latitude		22 Longitude		119b		
101	02	26 Driver's First Name Janice		Initial		Last Name Galeotafiore		29 Sex F		56 Driver's First Name		Initial		Last Name		59 Sex		120		
102	01	27 Number and Street 533 HERBERT LN		30 Eyes 2		57 Number and Street		60 Eyes		121										
103	01	28 City BRICK TOWNSHIP		State NJ		Zip 08724		58 City		State		Zip		122						
104	01	31 State		32 Drivers License No		33 DOB mm dd yy		34 Expires mm yy		61 State		62 Drivers License No		63 DOB mm dd yy		64 Expires mm yy		123		
105	11	35 Owner's First Name Janice		Initial		Last Name Galeotafiore		65 Owner's First Name		Initial		Last Name		124						
106	01	36 Number and Street 533 HERBERT LN		66 Number and Street		125														
107		37 City BRICK TOWNSHIP		State NJ		Zip 08724		67 City		State		Zip		126						
108	01	38 Make FORD		39 Model Fusion		40 Color White		41 Year 2009		42 Plate No. YLJ12N		43 State NJ		68 Make		69 Model		127		
109		44 VIN 3FAHP07Z19R174990		45 Expires 12 15		74 VIN		75 Expires		128a										
110	01	46 Vehicle Removed To Remained At Scene		47 Authority Owner		76 Vehicle Removed To		77 Authority Owner		128b										
111		48 Alcohol/Drug Test Given: ☒ No ☐ Yes ☐ Refused		134 Crash Diagram (NOT TO SCALE)		78 Alcohol/Drug Test Given: ☐ No ☐ Yes ☐ Refused		128c												
112	01	49 Hazardous Material On Board ☐ Spill ☐		50 Carrier No. ☐ USDOT ☒ Other *		79 Hazardous Material On Board ☐ Spill ☐		80 Carrier No. ☐ USDOT ☐ Other *		128d										
113		51 Commercial Vehicle Weight ☐ ≤ 10,000 lbs ☐ 10,001 - 26,000 lbs ☐ ≥ 26,001 lbs		52 Carrier name		81 Commercial Vehicle Weight ☐ ≤ 10,000 lbs ☐ 10,001 - 26,000 lbs ☐ ≥ 26,001 lbs		82 Carrier name		129a										
114		135 Crash Description SEE NARRATIVE		136 Damage To Other Property Metal post and flower pot with tree		137 Charge ☐ Multiple Charges		138 Summons No.		139 Charge ☐ Multiple Charges		140 Summons No.		130						
115		141 Officer's Signature Brian T Williams		142 Badge No. 0220		143 Reviewed By Arthur D Riv		144 Case Status ☐ Pending ☐ Complete		131										
116	04	145 Names & Addresses of Occupants - If Deceased, Date & Time of Death		146		147		148		149		150		151		152				
117		A 1 01 01 - 79 F - 09 04 Janice Galeotaf 533 HERBERT LN BRICK TOWNSHIP NJ 08724		B		C		D		E										

New Jersey Police Crash Investigation Report

Police Dept: NJ0150600 Code: 1

Motor Vehicle Crash Description

Station: Case No: 2015-00050334

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Crash occurred on the property of the RT 88 Car Wash, located at 1879 RT 88.

Driver #1 stated she had just come out of the car wash and went to hit the brakes, but the car wouldn't stop and she subsequently drove through a metal post and small tree in a flower pot.

A worker on scene, Damian Nieto, stated he was drying off another vehicle when he looked over and saw vehicle #1 coming out of the car wash quickly and then observed vehicle #1 strike the post and flower pot.

I sat in vehicle #1 and turned on the vehicle. I stepped on the brakes and they did not go to the floor. I then put the vehicle into gear and started to drive, ultimately stepping on the brakes several times. At no time did the vehicle not stop and the brakes appear to be working.

It appears as though when driver #1 put the vehicle into gear to pull out of the car wash, she inadvertently accelerated quickly and could not stop in time, subsequently striking the post and flower pot.

The post, which was filled with concrete, was knocked out of the ground and the flower pot was crushed as the vehicle drove into them.

Driver #1 advised she was not injured.

It should be noted that driver #1's daughter arrived on scene and she did not feel comfortable having her mother drive the car away so they left it parked and were going to call AAA to possibly have it towed.

Brian T Williams

0220

New Jersey Police Crash Investigation Report

Police Dept: NJ0150600 Code: 1

Motor Vehicle Crash Diagram

Station: _____ Case No: 2015-00050334

134 Crash Diagram (NOT TO SCALE)

 Indicate North

Brian T Williams

0220