

☐ Fatal

## New Jersey Police Crash Investigation Report

☒ Reportable☐ Non-Reportable☐ Change Report[illegible]

## New Jersey Police Crash Investigation Report

Police Dept: NJ0150600 Code: 1

## Motor Vehicle Crash Description

Station: Case No: 2015-00052626

(Refer to vehicle by number)

|   | Veh<br>Occ | Pos<br>In/On | Eject | Phys<br>Cond | Age  | Sex  | Loc<br>Inj | Type<br>Inj | Ref<br>Med | Equip<br>Avail | Equip<br>Used | Bag<br>Depl | Hosp<br>Code | Names & Addresses of Occupants - If Deceased, Date & Time of Death |
|---|------------|--------------|-------|--------------|------|------|------------|-------------|------------|----------------|---------------|-------------|--------------|--------------------------------------------------------------------|
| A | 83         | 84           | 85    | 86           | 87   | 88   | 89         | 90          | 91         | 92             | 93            | 94          | 95           | ----                                                               |
| B | ----       | ----         | ----  | ----         | ---- | ---- | ----       | ----        | ----       | ----           | ----          | ----        | ----         | ----                                                               |
| C | ----       | ----         | ----  | ----         | ---- | ---- | ----       | ----        | ----       | ----           | ----          | ----        | ----         | ----                                                               |
| D | ----       | ----         | ----  | ----         | ---- | ---- | ----       | ----        | ----       | ----           | ----          | ----        | ----         | ----                                                               |
| E | ----       | ----         | ----  | ----         | ---- | ---- | ----       | ----        | ----       | ----           | ----          | ----        | ----         | ----                                                               |

## 135 Crash Description

Vehicle 1 pulling into parking spot in parking lot of 1823 Route 88. Vehicle 2 parked legally and unoccupied in parking spot adjacent to spot into which Vehicle 1 is pulling into. Driver of Vehicle 1 stated that they turned too wide and struck Vehicle 2 while it was parked. Vehicle 1 crashes into Vehicle 2.

Based on my investigation and observations on scene I determined Vehicle 1 to be at fault for the motor vehicle crash.

This report completed by Ptl. Vendrell #228 of the Brick Township Police Department on 08/24/2015.

William Vendrell

0228

## New Jersey Police Crash Investigation Report

Police Dept: NJ0150600 Code: 1

### Motor Vehicle Crash Diagram

Station: \_\_\_\_\_ Case No: 2015-00052626

134 Crash Diagram (NOT TO SCALE)

○ Indicate North

This image shows a full page of blank graph paper. The grid consists of thin, light gray horizontal and vertical lines that intersect to form small squares across the entire surface. There are no margins, text, or other markings on the paper.

William Vendrell

0228