

96	Page 1 of 3	☐ Fatal	New Jersey Police Crash Investigation Report										☒ Reportable	☐ Non-Reportable	☐ Change Report				
05	1 Case Number 2015-00022936		10 Crash Occurred On: 1872 RT 88										11 Speed Limit		118a		02		
01	2 Police Dept of NJ0150600		Code 1		☐ At Intersection with Road Name Dir										12 Route No. Suffix		13 Milepost		118b
01	3 Station/Precinct				☐ Feet ☐ N ☐ E of: ☐ S ☐ W										18 Speed Limit		10		
09	4 Date of Crash mm dd yy		5 Day of Week Su M Tu W Th F Sa		6 Time (use 2400 hrs)		7 Municipality Code		8 Total Killed		9 Total Injured		19 Ramp To: From:		17 Cross Road Name		☐ NB ☐ EB ☐ SB ☐ WB		119a
01	0 4 1 5 1 5				1 6 0 5		1 5 0 6		0 0		0 0		21 Latitude		22 Longitude				119b
02	23 Veh No 01		24 Policy No C10001882		25 Ins Code 946		53 Veh No 02		54 Policy No 17363947		55 Ins Code 983		☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp to Emergency ☐ Hit & Run						120
01	26 Driver's First Name Christoph		Initial A		Last Name Benning		29 Sex M		56 Driver's First Name JAMES		Initial J		Last Name HOUGH		59 Sex M				121
01	27 Number and Street 39 ADELPHI RD				30 Eyes 4		57 Number and Street 14 ADAMSTON DR				60 Eyes								01
02	28 City South Toms River Borough		State		Zip 08757		58 City BRICK TOWNSHIP		State		Zip NJ 08723								
08	31 State NJ		32 Drivers License No B2565		33 DOB mm dd yy		34 Expires mm yy		61 State NJ		62 Drivers License No H6797		63 DOB mm dd yy		64 Expires mm yy				122
	1 2 4 6 1		1 2 9 5 4		12 22 1995		01 16		07 14 1942										
	35 Owner's First Name DIANE		Initial		Last Name SUMMERTON		65 Owner's First Name Maryann		Initial		Last Name Hough								123
	36 Number and Street 39 ADELPHIA RD				66 Number and Street														124
06	37 City SO TOMS RIVER		State		Zip		67 City		State		Zip								125
07	38 Make Chevrolet		39 Model		40 Color Gray		41 Year 2008		42 Plate No. N78BRF		43 State NJ		68 Make MERCEDES-BENZ		69 Model		70 Color Silver		126
04	44 VIN 2CNDL43F286007613		45 Expires 01 16		74 VIN WDBLJ65GX2T125994		75 Expires 05 15												11
01	46 Vehicle Removed To Remained At Scene		☐ Driven ☐ Left at Scene ☐ Towed ☐ Impound ☐ Disabled		47 Authority ☒ Owner ☒ Driver ☐ Police		76 Vehicle Removed To Driven Away		☐ Driven ☐ Left at Scene ☐ Towed ☐ Impound ☐ Disabled		77 Authority ☒ Owner ☒ Driver ☐ Police								127
01	48 Alcohol/Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0. - - % ☐ Pending		134 Crash Diagram (NOT TO SCALE)		Indicate North		78 Alcohol/Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0. - - % ☐ Pending												128a
01	49 Hazardous Material On Board ☐ Spill ☐ Name or Placard No.		SEE DIAGRAM PAGE				79 Hazardous Material On Board ☐ Spill ☐ Name or Placard No.												128b
03	50 Carrier No. ☐ USDOT ☒ Other *						80 Carrier No. ☐ USDOT ☒ Other *												128c
04	51 Commercial Vehicle Weight ☐ ≤ 10,000 lbs ☐ 10,001 - 26,000 lbs ☐ ≥ 26,001 lbs						81 Commercial Vehicle Weight ☐ ≤ 10,000 lbs ☐ 10,001 - 26,000 lbs ☐ ≥ 26,001 lbs												128d
	52 Carrier name						82 Carrier name												129a
	135 Crash Description																		129b
	SEE NARRATIVE																		129c
	136 Damage To Other Property None																		129d
	137 Charge 1 39:3-10		☐ Multiple Charges		138 Summons No. E15003377		139 Charge 1 39:4-97		☐ Multiple Charges		140 Summons No. E15003378								130
	141 Officer's Signature William Vendrell				142 Badge No. 0228		143 Reviewed By Jason M Matt		Badge No. 0210		144 Case Status ☐ Pending ☐ Complete								06
A	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants - If Deceased, Date & Time of Death					06
B	1	01	01	-	19	M	-	-	-	09	04	-	-	Christoph A Benn 39 ADELPHI RD South Toms River Borough 08757					131
C	1	03	01	-	-	F	-	-	-	09	04	-	-	Kelly Summerton 41 ADELPHI South Toms River 08757					06
D	2	01	01	-	72	M	-	-	-	09	04	-	-	JAMES J HOUGH 14 ADAMSTON DR BRICK TOWNSHIP NJ 08723					132
E	2	03	01	-	-	-	-	-	-	09	04	-	-	Maryann Hough					03
	-	-	-	-	-	-	-	-	-	-	-	-	-						133

New Jersey Police Crash Investigation Report

Police Dept: NJ0150600 Code: 1

Motor Vehicle Crash Description

Station: Case No: 2015-00022936

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	----
B	---	---	---	---	---	---	---	---	---	---	---	---	---	----
C	---	---	---	---	---	---	---	---	---	---	---	---	---	----
D	---	---	---	---	---	---	---	---	---	---	---	---	---	----
E	---	---	---	---	---	---	---	---	---	---	---	---	---	----

135 Crash Description

Driver of Vehicle 1 parked in parking spot in parking lot of Walmart located at 1872 Route 88. Vehicle 2 traveling through parking lot in area of Vehicle 1. Driver of Vehicle 1 stated that they started to back out of parking spot and did not observe Vehicle 2 traveling behind them. Vehicle 1 crashes into Vehicle 2.

Driver of Vehicle 2 stated that as they were traveling through the lane in the parking lot Vehicle 1 pulled out of a parking spot and crashed into their vehicle as they traveled behind them.

Based on my investigation and observations on scene I determined Vehicle 1 to be at fault for the motor vehicle crash.

This report completed by Ptl. Vendrell #228 of the Brick Township Police Department on 04/15/2015.

William Vendrell

0228

New Jersey Police Crash Investigation Report

Police Dept: NJ0150600 Code: 1

Motor Vehicle Crash Diagram

Station: _____ Case No: 2015-00022936

134 Crash Diagram (NOT TO SCALE)

 Indicate North

This image shows a full page of blank graph paper. The grid consists of thin, light gray horizontal and vertical lines that intersect to form small squares across the entire surface. There are no margins, text, or other markings on the paper.

William Vendrell

0228