

96	05	Page 1 of 3		Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report															
97	01	1 Case Number		2014-00018530										10 Crash Occurred On:		1551 Rt 88		11 Speed Limit				118a													
98	01	2 Police Dept of		Code		3 Station/Precinct		4 Date of Crash		5 Day of Week		6 Time		7 Municipality Code		8 Total Killed		9 Total Injured		118b															
99	07	Brick PD		01		---		03 22 14		Su M Tu W Th F Sa		13 26		1506		---		---		10															
100	01	23 Veh No		24 Policy No.		25 Ins Code		53 Veh No		54 Policy No.		55 Ins Code								119a															
101	02	1		809013976		012		2												119b															
102	01	26 Driver's First Name		Initial		Last Name		29 Sex		56 Driver's First Name		Initial		Last Name		59 Sex				120															
103	01	John E Hannen						M												121															
104	01	27 Number and Street		173 Glen Ridge CT				30 Eyes		57 Number and Street				60 Eyes						---															
105	08	28 City		Brick		New Jersey		08724		58 City				State		Zip				122															
106	---	31 State		NJ		32 Drivers License No		H0451 40765 12554		33 DOB		12 28 55		34 Expires		01 17				---															
107	---	35 Owner's First Name		Initial		Last Name		65 Owner's First Name		Initial		Last Name								123															
108	05	Pamela L Hannen						66 Number and Street				67 City				State		Zip		---															
109	---	36 Number and Street		173 Glen Ridge CT				68 Make		69 Model		70 Color		71 Year		72 Plate No.		73 State		124															
110	01	37 City		Brick		New Jersey		08724		74 VIN				75 Expires						125															
111	---	38 Make		DODGE		39 Model		Ram 1500		40 Color		Silver		41 Year		2002		42 Plate No.		---															
112	---	43 State		NJ		44 VIN		1D7HA16K52J176477		45 Expires		04 14		76 Vehicle Removed To		☒ Driven		☐ Left at Scene		126															
113	---	46 Vehicle Removed To		☒ Driven		☐ Left at Scene		☐ Towed		☐ Impound		☐ Disabled		47 Authority		☒ Owner		☐ Driver		127															
114	---	48 Alcohol/Drug Test		Given: ☒ No ☐ Yes ☐ Refused		Type: ☐ Breath ☐ Blood ☐ Urine		Results: 0. ___ % ☐ Pending		78 Alcohol/Drug Test		Given: ☐ No ☐ Yes ☐ Refused		Type: ☐ Breath ☐ Blood ☐ Urine		Results: 0. ___ % ☐ Pending				128a															
115	---	49 Hazardous Material		On Board ☐ Spill ☐		Name or Placard No.		50 Carrier No.		☐ USDOT ☐ Other *		79 Hazardous Material		On Board ☐ Spill ☐		Name or Placard No.		80 Carrier No.		128b															
116	02	51 Commercial Vehicle Weight		☐ ≤ 10,000 lbs		☐ 10,001 - 26,000 lbs		☐ ≥ 26,001 lbs		81 Commercial Vehicle Weight		☐ ≤ 10,000 lbs		☐ 10,001 - 26,000 lbs		☐ ≥ 26,001 lbs		82 Carrier name		128c															
117	---	52 Carrier name																		128d															
134 Crash Diagram (NOT TO SCALE)																				136 Damage To Other Property		Light Stanchion belonging to B.T.M.U.A. was struck and is leaning slightly		137 Charge		☐ Multiple Charges		138 Summons No.		139 Charge		☐ Multiple Charges		140 Summons No.	
141 Officer's Signature																				Mark		Nixon		142 Badge No.		209		143 Reviewed By		Hine		144 Case Status		☐ Pending ☒ Complete	
83 84 85 86 87 88 89 90 91 92 93 94 95																				Names & Addresses of Occupants - If Deceased, Date & Time of Death															
A																				1		01		01		---		58		M		---		09 04	
B																																			
C																																			
D																																			
E																																			

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2014-00018530**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle # 1 was attempting to make a K-turn in the driveway of the B.T.M.U.A. (1551 Rt. 88). While backing up, Vehicle # 1 struck a light stanchion belonging to the B.T.M.U.A. Representatives from the B.T.M.U.A. were on scene, observed the motor vehicle crash and requested a Motor Vehicle Accident Report. It should be noted that the light stanchion was leaning slightly but presented no hazardous condition. Driver # 1 stated that he did not see the light stanchion behind him as he backed his vehicle up into the K-turn.

MarkNixon209

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: **Brick PD**


Code: **01-Municipal Police**

Station: **---**

Case No: **2014-00018530**

134 Crash Diagram (NOT TO SCALE)

○ Indicate North



Mark

Nixon

209