

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2014-00026135**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Vehicle 1 and Vehicle 2 were both in the parking lot of the Home Depot located at 1722 RT 88 in Brick. Vehicle 1 was backing out of a handicap parking space. Vehicle 2 was traveling southbound through the travel lane as Vehicle 1 continued a wide radius turn while backing out of the parking spot. As Vehicle 1 was backing, the left rear corner struck the left rear passenger door of Vehicle 2. The driver of Vehicle 1 stated that he was in a rush to back out of his spot as another car was waiting to pull into it.

No injuries were reported at the scene. No motor vehicle summonses were issued. Both vehicles were driven from the scene.

ChristopherGeskey184

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD

Code: 01-Municipal Police

Station: ---

Case No: 2014-00026135


134 Crash Diagram (NOT TO SCALE)

○ Indicate North

Home Depot Store
1722 RT 88, Brick



NOT TO SCALE



Christopher

Geskey

184