

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: _____ Case No: **2014-00034177**

(Refer to vehicle by number)

G															Names & Addresses of Occupants - If Deceased, Date & Time of Death
Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code			
ALL INVOLVED	F	83	84	85	86	87	88	89	90	91	92	93	94	95	
	G														
	H														
	I														
	J														

135 Crash Description

The owner of vehicle number two stated while the vehicle was parked, unoccupied, in the parking lot 1640 Rt. 88, an unknown vehicle struck the front lower passenger side bumper. Upon further investigation fresh white paint was observed on the damaged portion of the vehicle. A check of the surrounding area was conducted with negative results for the suspect vehicle.

Keith

Prendeville

223

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD



Code: 01-Municipal Police

Station: _____

Case No: 2014-00034177


134 Crash Diagram (NOT TO SCALE)

○ Indicate North



NOT TO SCALE

unknown how vehicle number one caused the crash



Keith

Prendeville

223