

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2014-00052641**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
	83	84	85	86	87	88	89	90	91	92	93	94	95		
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Bicyclist 1 was riding a bicycle that was for sale at Brick Bikes on Rt. 88. The bicyclist was riding in a southerly direction through the parking lot behind Brick Bikes, in the area of the iHop restaurant at 1759 Rt. 88. Vehicle 2 was proceeding in an easterly direction through the same parking lot, through a row of parked cars.

As Vehicle 2 emerged from the row of parked cars and entered into the open part of the parking lot that the bicyclist was riding through, the driver saw the bicycle coming directly towards her vehicle, from her left side. Driver 2 stopped her vehicle just as the bicyclist crashed into Vehicle 2. The bicyclist then fell over the handlebars and rolled onto the hood of Vehicle 2.

Bicyclist 1 stated that his hands were on a part of the handlebars that did not have access to the hand brakes. When he saw Vehicle 2 enter the area where he was test driving the bicycle, he tried squeezing for the hand brakes, but as his hands were not on the area of the handlebars where the hand brakes were located, he was unable to stop. This caused him to crash into Vehicle 2. Bicyclist 1 stated that it was his fault, and that Vehicle 2 was not going fast.

Driver 2 stated that as she came through the row of parked cars, she slowed at the end of the row because there is commonly some traffic that intersects in that area. She then proceeded to go through the parking lot, but saw the bicyclist coming directly at her vehicle. She then came to a stop just as the bicyclist collided with her vehicle.

Bicyclist 1 was transported to Brick Hospital for a stiff neck and back. The bicycle was returned to its owner, Brick Bikes.

JamesKelly233

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD


Code: 01-Municipal Police

Station: ---

Case No: 2014-00052641

134 Crash Diagram (NOT TO SCALE)

○ Indicate North



James

Kelly

233