

96	05	Page 1 of 3		New Jersey Police Crash Investigation Report		☒ Reportable		☐ Non-Reportable		☐ Change Report		118a
97	01	1 Case Number		2013-00057359		10 Crash Occurred On: 1872 Rt. 88		11 Speed Limit				99
98	01	2 Police Dept of		Brick PD		Code 01		3 Station/Precinct				118b
99	09	4 Date of Crash		mm dd yy		5 Day of Week		Su M Tu W Th F Sa		6 Time (use 2400 hrs)		25
100	01	09		14		13		1		134		119a
101	02	23 Veh No		24 Policy No.		25 Ins Code		53 Veh No		54 Policy No.		119b
102	01	1		Parked		Ped		Pedalcyclist		Resp to Emergency		120
103	01	26 Driver's First Name		Initial		Last Name		29 Sex		56 Driver's First Name		01
104	02	31 State		32 Drivers License No		33 DOB mm dd yy		34 Expires mm yy		61 State		121
105	99	NJ		D2110		40475		55832		050583		---
106	02	35 Owner's First Name		Initial		Last Name		65 Owner's First Name		Initial		122
107	02	36 Number and Street		11 Longpoint DR		37 City		State		Zip		---
108	01	38 Make		39 Model		40 Color		41 Year		42 Plate No.		123
109	01	JEEP		Grand Cherokee		Gray		2004		G431UF		---
110	01	44 VIN		1J4GW48S14C387523		45 Expires		11		13		124
111	01	46 Vehicle Removed To		Driven		Left at Scene		Towed		Impound		14
112	---	48 Alcohol/Drug Test		Given: No		Yes		Refused		Type: Breath		125
113	---	49 Hazardous Material		Name or Placard No.		On Board		Spill		79 Hazardous Material		08
114	---	50 Carrier No.		USDOT		Other *		80 Carrier No.		USDOT		---
115	---	51 Commercial Vehicle Weight		≤ 10,000 lbs		10,001 - 26,000 lbs		≥ 26,001 lbs		81 Commercial Vehicle Weight		54
116	01	52 Carrier name				82 Carrier name				129a		26
117	03	53				83				129b		---
See Attached Pages												129c
See Attached Pages												129d
See Attached Pages												130
136 Damage To Other Property												06
Walmart												131
137 Charge												12
138 Summons No.												132
139 Charge												133
140 Summons No.												---
141 Officer's Signature												134
Joseph Farnkopf												135
142 Badge No.												136
143 Reviewed By												137
144 Case Status												138
145												139
Names & Addresses of Occupants - If Deceased, Date & Time of Death												140
A												141
B												142
C												143
D												144
E												145

New Jersey Police Crash Investigation Report Motor Vehicle Crash Description	Police Dept: Brick PD Code: 01-Municipal Police Station: --- Case No: 2013-00057359
---	--

(Refer to vehicle by number)

G														
Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death	
83	84	85	86	87	88	89	90	91	92	93	94	95		
F														
G														
H														
I														
J														

135 Crash Description

Investigation at the scene revealed that Vehicle #1 had parked directly in front of the main entrance at the Walmart store at 1872 Route 88.. Vehicle #2 then pulled directly behind Vehicle #1, in front of the main entrance.

The driver of Vehicle #1(P1) stated that she pulled in front of the store to drop her mother of at the entrance. She stated that Vehicle #2 pulled directly behind her and blew her horn repeatedly. She stated that as her mother (P2) was exiting the passenger side of her vehicle, she exited the drivers seat to speak to the driver of Vehicle #2. The driver of Vehicle #1 stated that she was then struck by her door or the frame of the vehicle as she exited. She stated that she was struck in the head and pushed to the ground.

I spoke to the driver of Vehicle #2 about the accident. She stated that she stopped for Vehicle #1 as it was parked in front of the store. She stated that she waited several seconds and blew her horn as the vehicle was holding up traffic. She stated that Vehicle #1 failed to move and that she blew her horn several more times. She stated that she did not see the elderly passenger getting out of the passenger side of the vehicle and that she believed that Vehicle #1 was illegally parked in front of the store. She stated that she observed the driver of Vehicle #1 exit the vehicle and that the vehicle traveled backwards and struck her with the door. She stated that Vehicle #1 traveled backwards and struck the front end of her vehicle. She stated that she backed up after the accident and that Vehicle #1 continued reversing, striking a flower stand in the front of Walmart.

I then watched the surveillance video from Walmart and observed the incident. It appears that the driver of Vehicle #1 had placed the gear select in reverse before exiting the vehicle. The video shows the passenger in Vehicle #1 exiting the vehicle and getting struck by the passenger side front door. The passenger is knocked to the ground and the vehicle front tire narrowly misses running her over. Vehicle #1 quickly moved backwards and then struck the front end of Vehicle #2. Vehicle #2 then backed up after the collision and Vehicle #1 then continued in reverse, striking a cement vehicle barrier before colliding with a flower stand.

The driver of Vehicle #1 complained of head pain and was transported to Brick ER for medical assistance. She was later released after her tests were completed. The passenger in Vehicle #1 complained of hip pain and was transported to Brick ER. She was treated and released. The driver of Vehicle #2 was not injured.

It should be noted that Vehicle #1 is covered by Garrison Property and Casualty Insurance from 9800 Fredericksburg Road in San Antonio, Texas 78288 with policy #030522155R71078. The surveillance video from Walmart was placed into property. The driver of Vehicle #1 was issued a summons for Careless Driving.

Joseph

Farnkopf

173

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD


Code: 01-Municipal Police

Station: ---

Case No: 2013-00057359

134 Crash Diagram (NOT TO SCALE)

○ Indicate North



Joseph

Farnkopf

173