

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2014-00011634**

(Refer to vehicle by number)

	G	Veh	Pos	Eject	Phys	Age	Sex	Loc	Type	Ref	Equip	Equip	Bag	Hosp	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		Occ	In/On		Cond			Inj	Inj	Med	Avail	Used	Depl	Code	
ALL INVOLVED	F	83	84	85	86	87	88	89	90	91	92	93	94	95	
	G														
	H														
	I														
J															

135 Crash Description

Investigation at the scene indicated the following: Vehicle 2 was parked, unoccupied, in the Walmart parking lot. The unknown vehicle 1 contacted vehicle 2's front. Vehicle 1 fled the scene prior to police arrival.

The operator of vehicle 2, Douglas Reiss, stated he parked his vehicle in the Walmart parking lot at approximately 1325 hours on February 22, 2014 and then went into the store. He stated he returned to his vehicle approximately 20 minutes later and found that the front of it had been struck.

Vehicle 2 is a work truck rented by Belfor USA.

There are no known witnesses. There is no surveillance camera coverage of the parking lot where the crash occurred. There was no crash debris near the reported crash site.

Vehicle 2 had not been moved prior to police arrival. It was parked 6 spaces from the Walmart parking lot service roadway that parallels Jack Martin Boulevard in the 3rd full set of parking lanes from State Route 88.

JosephOliveri141

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: **Brick PD**

Code: **01-Municipal Police**

Station: **---**




Case No: **2014-00011634**

134 Crash Diagram (NOT TO SCALE)

 Indicate North

Jack Martin Boulevard 

Walmsot Parking Lot Service Road



Joseph

Oliveri

141