

NJ Accident Report Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD** Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---** Case No: **2013-00075816**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
F															
G															
H															
I															
J															

135 Crash Description

Vehicle 1 and 2 were traveling the parking lot of the Walmart (1872 Route 88). Vehicle 1 was parked in 4th space of row #9 facing south and Vehicle 2 was parked in the sixth space of row #8 facing north. Vehicle 2 backed from the parking space into the thoroughfare between the rows and started forward travel. Vehicle 1 backed from the parking space into the thoroughfare between the rows and struck the driver side of Vehicle 2. Minor damage noted to the driver side of Vehicle 2 and no damage was observed to Vehicle 1. No injuries were reported at the scene and both vehicles were able to be driven away.

Glenn Turner

Officer's Signature

178

Badge Number

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD


Code: 01-Municipal Police

Station: ---


Case No: 2013-00075816

134 Crash Diagram (NOT TO SCALE)

○ Indicate North



Walmart
1872 Route 88



Glenn

Turner

178