

96	05	Page 1 of 3		Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report						
97	01	1 Case Number		2013-00072378										10 Crash Occurred On: Rt 88		11 Speed Limit		8 8				118a				
98	01	2 Police Dept of		Brick PD										Code		01		12 Route No.		Suffix		118b				
99	02	3 Station/Precinct		---										500.00		☒ Feet		☒ N		Edge ST		119a				
100	01	4 Date of Crash		mm		dd		yy		5 Day of Week		Su M Tu W Th F Sa		6 Time (use 2400 hrs)		7 Municipality Code		8 Total Killed		9 Total Injured		119b				
101	02	23 Veh No		24 Policy No.		25 Ins Code		53 Veh No		54 Policy No.		55 Ins Code		14		15		16		19 To:		20 Route/Name		120		
102	02	26 Driver's First Name		Initial		Last Name		29 Sex		56 Driver's First Name		Initial		Last Name		30 Eyes		57 Number and Street		59 Sex		60 Eyes		121		
103	02	27 Number and Street		9 Sun Hollow RD		State		Zip		58 City		State		Zip		31 State		32 Drivers License No		33 DOB mm dd yy		34 Expires mm yy		122		
104	02	28 City		Howell		New Jersey		07731-		Brick		New Jersey		08723-		NJ		G5272 09674 58932		08 19 93		08 14		123		
105	03	35 Owner's First Name		Initial		Last Name		65 Owner's First Name		Initial		Last Name		36 Number and Street		9 Sun Hollow RD		66 Number and Street		1112 Industrial PKWY		67 City		State		124
106	---	37 City		Howell		New Jersey		07731-		Brick		New Jersey		08724-		NJ		38 Make		39 Model		40 Color		41 Year		125
107	---	38 Make		JEEP		LIBERTY		White		2009		V81AFJ		NJ		43 State		68 Make		69 Model		70 Color		71 Year		126
108	01	44 VIN		1J8GN28K49W510100		45 Expires		10 14		74 VIN		1FTSS34L15HB50250		75 Expires		10 14		46 Vehicle Removed To		☒ Driven		☐ Left at Scene		☐ Towed		127
109	03	46 Vehicle Removed To		☒ Driven		☐ Left at Scene		☐ Towed		47 Authority		☒ Owner		☒ Driver		☒ Police		76 Vehicle Removed To		☒ Driven		☐ Left at Scene		☐ Towed		128a
110	01	48 Alcohol/Drug Test		Given: ☒ No ☐ Yes ☐ Refused		Type: ☐ Breath ☐ Blood ☐ Urine		Results: 0. ___ % ☐ Pending		49 Hazardous Material		Name or Placard No.		78 Alcohol/Drug Test		Given: ☒ No ☐ Yes ☐ Refused		Type: ☐ Breath ☐ Blood ☐ Urine		Results: 0. ___ % ☐ Pending		79 Hazardous Material		Name or Placard No.		128b
111	02	49 Hazardous Material		On Board		Spill		50 Carrier No.		☐ USDOT ☐ Other *		51 Commercial Vehicle Weight		☐ ≤ 10,000 lbs		☐ 10,001 - 26,000 lbs		☐ ≥ 26,001 lbs		82 Carrier name		83		84		128c
112	---	50 Carrier No.		☐ USDOT ☐ Other *		51 Commercial Vehicle Weight		☐ ≤ 10,000 lbs		☐ 10,001 - 26,000 lbs		☐ ≥ 26,001 lbs		82 Carrier name		83		84		85		86		87		128d
113	---	51 Commercial Vehicle Weight		☐ ≤ 10,000 lbs		☐ 10,001 - 26,000 lbs		☐ ≥ 26,001 lbs		82 Carrier name		83		84		85		86		87		88		89		129a
114	---	52 Carrier name		83		84		85		86		87		88		89		90		91		92		93		129b
115	---	52 Carrier name		83		84		85		86		87		88		89		90		91		92		93		129c
116	04	52 Carrier name		83		84		85		86		87		88		89		90		91		92		93		129d
117	03	52 Carrier name		83		84		85		86		87		88		89		90		91		92		93		130
136 Damage To Other Property None																								130		
137 Charge ☐ Multiple Charges																								131		
138 Summons No.																								132		
139 Charge ☐ Multiple Charges																								133		
140 Summons No.																								134		
141 Officer's Signature																								135		
Brenden Barnes																								136		
142 Badge No.																								137		
143 Reviewed By																								138		
Gerling																								139		
144 Case Status																								140		
☐ Pending ☒ Complete																								141		
Names & Addresses of Occupants - If Deceased, Date & Time of Death																								142		
A																								143		
B																								144		
C																								145		
D																								146		
E																								147		

New Jersey Police Crash Investigation Report

Police Dept: **Brick PD**Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **---**Case No: **2013-00072378**

(Refer to vehicle by number)

ALL INVOLVED	G	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
		83	84	85	86	87	88	89	90	91	92	93	94	95	
	F														
	G														
	H														
	I														
	J														

135 Crash Description

Investigation reveals vehicle 2 was traveling East on Rt.88 approaching the entrance/ exit to 1623 Rt.88. Vehicle 1 was traveling West on Rt. 88 approaching 1623 Rt.88. Driver of vehicle 2 states vehicle 1 cut him off as vehicle 1 made a left in front of his van. Driver of vehicle 1 states she cut off vehicle 2 as she made a left into 1623 Rt. 88 and vehicle 2 struck her. No injuries were reported on scene.

BrendenBarnes197

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram


Police Dept: Brick PD

Code: 01-Municipal Police

Station: ---

Case No: 2013-00072378

134 Crash Diagram (NOT TO SCALE)



Brenden

Barnes

197